DELAWARE STATE HISTORIC PRESERVATION OFFICE

7	8	. \		15	THE GREEN,	DOVER, DE 19901
		CULTURAL RESO	LIRCE SURVEY		CRS#	K-7375
	\mathbf{m}	PROPERTY IDENT			SPO Map	
A		I KOLEKII IDENI	II ICATION FOR	KIAI	or o map	South
					Hundred	Murderkill
						Frederica
					Quad	riederica
					Other	
1.	HIST	ORIC NAME/FUNCTION:	L. Webb/Residence	е		
2.	ADDI	RESS/LOCATION: West S	Side of SR 1; 6947 E	Bay Road		
3.	TOW	N/NEAREST TOWN: Fred	erica			vicinity?
4.	MAIN	TYPE OF RESOURCE:	building 🛭 landscape 🗌	structure district	□ site	object
5.	MAIN	FUNCTION OF PROPERTY	: Residence			
6.	PRO	JECT TITLE/ REASON FOR	SURVEY (if applica	able):		
		Little Heaven Interchange				
7.	ADDITI	ONAL FORMS USED:				
	#:	Form:	List	property types:		
	1	CRS 2 Main Building Form	n Hous			
	3	CRS 3 Secondary Building		rehouses, 1 gara	ae	
	0	CRS 4 Archaeological Site		, ,		
	0	CRS 5 Structure (Building	-Like) Form			
	0	CRS 6 Structure (Land Fe	ature) Form			
	0	CRS 7 Object Form				
	0	CRS 8 Landscape Elemen	ts Form			
	0	CRS 9 Map Form	N/A			
	0	CRS 14 Potential District	Form			
8. 3	SURVE	YOR INFORMATION:				
	Survey	or name:	Lauren C. Archib	ald and Christine	Tate	
	Principa	al Investigator name:	Lauren C. Archib	ald		
	Principal Investigator signature:					

Date: July 2004

Organization:

A.D. Marble & Company

Q.	OTHER	NOTES	OR	OBSERV	/ATIONS:

CRS#	K-7375
A 1 1 2 3 27	11-1010

10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check all a	ppropriate boxes; refer to state management
a) Time period(s)	Pre-European Conta Paleo-Indian Archaic Woodland I Woodland II	ct
	1600-1750∀ Contact Period (N 1630-1730∀ Exploration and F 1730-1770∀ Intensified and Du 1770-1830∀ Early Industrializa 1830-1880∀ Industrialization a 1880-1940∀ Urbanization and 1940-1960∀ Suburbanization a	rontier Settlement urable Occupation ution und Early Urbanization Early Suburbanization
b) Geographical zone	☐ Piedmont ☐ Upper Penins ☐ Lower Penins ☐ Coastal ☐ Urban (City of	ula/Cypress Swamp
c) Historic period them	e(s)	
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	K-7375

1.	ADDRESS/LOCATION: West Side of SR 1; 6947 Bay Road	
2.	FUNCTION(S): historic Dwelling current Dwelling	
3.	YEAR BUILT: 1948 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE OR FLOOR PLAN: Vernacular	
5.	INTEGRITY: original site	year
	list major alterations and additions with years (if known) a. Porch enclosed on southern elevation b. First floor of northern elevation extended	<u>year</u> 1965 1965
6.	CURRENT CONDITION: excellent good fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leavelenks.)	e no
	a. Overall shape: Rectangular Stories: 1.5 Additions: Enclosed porch and first floor enlarged	
	b Structural system (if known): Frame	
	c. Foundation: materials: Concrete block basement: full ☐ partial ☒ not visible ☐ no basement ☐	
	d. Exterior walls (original if visible& any subsequent coverings): Aluminum siding	
	e. Roof: shape: Gable (side) materials: Asphalt shingle cornice: Aluminum dormers: Asphalt shingle chimney: location(s): Exterior, façade	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: Direction: E 1) Bays 5 2) Windows 4 fenestration Irregular type Casement, fixed, and double hungvinyl and wood trim Aluminum shutters Fixed vinyl	

```
Facade (cont'd)
                         1
          Door(s)
             location
                         Off-center
                         Single arched-top single-light vertical plank
             type
             trim
                         Single sheltered brick step
    4)
          Porch(es)
b.
    Side: Direction: N
    1)
          Bays
                         3
    2)
          Windows
                         3
             fenestration Irregular
                         One tripartite 6/1 and two 1/1 sash with diagonal mullions
             type
                         Aluminum
             trim
                         Fixed vinyl
             shutters
    3)
          Door(s)
                         n/a
                         n/a
             location
             type
                         n/a
                         n/a
             trim
     4)
          Porch(es)
                         n/a
    Side: Direction: S
C.
                         3
     1)
          Bays
          Windows
                         3
     2)
             fenestration Regular
                         Vinyl casement
             type
             trim
                         Aluminum
                         Fixed vinyl
             shutters
     3)
          Door(s)
                         On enclosed porch
             location
                         Metal replacement
             type
                         Aluminum
             trim
                         Unsheltered steps to enclosed porch
     4)
          Porch(es)
d.
     Rear: Direction: W
                         6
          Bays
                         6
     2)
          Windows
             fenestration Irregular
                         Casement, fixed, oriel, and double hung--vinyl and wood
             type
                         Aluminum
             trim
                         Fixed vinyl
             shutters
     3)
          Door(s)
                         n/a
             location
                         n/a
                         n/a
             type
```

9. INTERIOR: n/a

4)

10. LANDSCAPING: Asphalt driveway, mature trees

trim

Porch(es)

n/a

n/a

11. OTHER COMMENTS: n/a



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS # **K-7375**

1.	ADDRESS/LOCATION: West Side of SR 1; 6947 Bay Road	
2.	FUNCTION(S): historic Warehouse I current Cold storage	
3.	YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN: Vernacular	
5.	INTEGRITY: original site	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent ☐ good ☒ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1.5	
	c. Wall coverings Aluminum in gable ends	
	d. Foundation Concrete block on poured concrete pad	
	e. Roof structural system Frame coverings Asphalt shingle openings n/a	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: N1) bays: 12) windows: n/a	
	3) door(s): 1 large hinged wood door	
	4) other: n/a	

CRS#	K-7375
	N = / .5 / .7

	1) 2)	bays: 1 windows: n/a
	3)	door(s): n/a
	4)	other: Small attached shed-roof shelter for compressor
c.	1) 2)	le: direction: E bays: 1 windows: n/a door(s): n/a
	4)	other: n/a
d.	1)	ar: direction: S bays: 1 windows: n/a
	3)	door(s): n/a
	4)	other: n/a
INTE	RIO	R (if accessible):
a) FI	oor	plan n/a
L) D	4:4:	Santualla m/a
b) Pa	artiti	on/walls n/a
c) Fi	nish	nes n/a
d) F	urnis	shings/machinery n/a

b. Side: direction: W

9.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	K-7375	

1.	ADDRESS/LOCATION: West Side of SR 1; 6947 Bay Road	
2.	FUNCTION(S): historic Warehouse II current Equipment storage	
3.	YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN:	
5.	INTEGRITY: original site moved	
	if moved, from where original location's CRS #	year
	list major alterations and additions with years (if known) a.	year
	b.	
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1.5	
	c. Wall coverings Aluminum in gable ends	
	d. Foundation Concrete block on poured concrete pad	
	e. Roof structural system Frame coverings Asphalt shingle openings n/a	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: N1) bays: 22) windows: n/a	
	3) door(s): Two oversized, three-light, wood panel overhead garage doors	
	4) other: n/a	

CRS#	K-7375
(D T	14 - / 5 / 5
UNDIF	11-1313

	1) 2)	bays: 1 windows: n/a		
	3)	door(s): n/a		
	4)	other: n/a		
c.	Sid 1) 2)	e: direction: E bays: 2 windows: One 2/2 aluminum sash		
	3)	door(s): One single metal-clad replacement pedestrian		
	4)	other: n/a		
d.	1)	bays: n/a windows: n/a		
	3)	door(s): n/a		
	4)	other: n/a		
MITE	DIOF			
INTERIOR (if accessible):				
a) Flo	oor p	olan Open		
b) Partition/walls None				
c) Finishes None				
d) Furnishings/machinery Staircase to attic in southeast corner				

b. Side: direction: W

9.



CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	K-7375	

1.	ADDRESS/LOCATION: West Side of SR 1; 6947 Bay Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN: Vernacular	
5.	INTEGRITY: original site moved	
	if moved, from where original location's CRS #	year
	list major alterations and additions with years (if known) a.	year
	b.	
6.	CURRENT CONDITION: excellent ⊠ good □ fair □	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vinyl siding	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Asphalt shingle openings Ventilator in center (cupola)	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: E1) bays: 22) windows: n/a	
	3) door(s): 2 ovehead garage doors	
	4) other: n/a	

CRS#	K-7375
LRSI	N-1.5/3

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: Two 6/6 sash
 - 3) door(s): n/a
 - 4) other: n/a
- c. Side: direction: S
 - 1) bays: 2
 - 2) windows: Two 6/6 sash
 - 3) door(s): n/a
 - 4) other: n/a
- d. Rear: direction: W
 - 1) bays: Not visible
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: Not visible
- 9. INTERIOR (if accessible):
 - a) Floor plan
- n/a
- b) Partition/walls
- n/a
- c) Finishes
- n/a
- d) Furnishings/machinery
- n/a


CULTURAL RESOURCE SURVEY MAP FORM

CRS#	K-7375
------	--------

1.	ADDRESS/LOCATION: 6947 Bay Road, South Murderkill Hundred, Kent County
2.	NOT FOR PUBLICATION reason:
3.	LOCATION MAP:
	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

CRS #K-7375 L. Webb Property

Dwelling. This mid-twentieth-century, one-and-one-half-story, side-gable vernacular cottage (built ca. 1948) is the first and northernmost of three similar homes built on adjoining lots along what is now SR 1. It features an asphalt shingle roof with cross-gable and shed dormers, aluminum siding and trim, and a concrete block foundation. On the five-bay asymmetrical façade (eastern elevation) are three tripartite replacement windows. They are in various combinations of casement, fixed, and double-hung sash types. The main entrance is a single arched door with a brick surround. According to the original and current owner, who still occupies it, the house has been "upgraded many times" (Ruth Webb, personal communication). The most significant changes have been made to the sides of the house. The porch on the southern elevation has been enclosed and finished, and the first floor on the north side has been extended (both ca. 1965).

Garage. Behind the house and to its south sits a large, hipped-roof, two-car frame garage built ca. 1960. It has a concrete block foundation on a poured concrete slab, an asphalt shingle roof with a small cupola, and vinyl siding. There are two overhead garage doors on the façade (eastern elevation) and matching pairs of six-over-six replacement windows with fixed shutters on the northern and southern elevations.

Warehouse I. Although the two outbuildings on this lot are screened by a tall fence and used by the produce stand on the adjoining lot, they are part of the dwelling tax parcel. The smaller of the two "warehouses", both built ca. 1955, is a one-and-one-half-story, gable end, concrete-block structure on a poured concrete pad foundation. It has one large hinged door at the eastern corner of the façade (northern elevation), a smaller hinged door in the gable end of the same side, and a small shed-roofed extension which shelters a compressor on the western elevation. It is used for cold storage.

Warehouse II. The larger "warehouse" is immediately to the west of the smaller one. It too is a one-and-one-half-story, gable end, concrete-block structure on a poured concrete pad foundation. On its façade (northern elevation) are two oversized overhead garage doors large enough for commercial trucks. On the eastern elevation are a pedestrian entrance and a window. There are two windows on the western elevation, while the back is blind. The interior is unobstructed with the exception of a staircase to the attic story.

Historical Background. The L. Webb Property located near Frederica, Delaware dates from ca. 1948. In December 1911, William Townsend conveyed the property to Jester A. Gray through the Orphans Court of Kent County (KCDB R2: 300). On July 20, 1916, Jester A. and Sallie B. Gray sold the property containing 85.0 acres along with the "...farm, tract, piece or parcel of land...and all singular buildings and improvements" to Liston H. Webb for \$8,566.88 (KCDB A11: 177). On February 25, 1949, Liston H. Webb conveyed a "small part" of the 85.0 acres property along with "...all singular buildings and improvements" to Liston H. Webb, Jr. and Ruth Webb (KCDB N18: 204).

Evaluation: The L. Webb Property (residence) at 6947 Bay Road is recommended not eligible for listing in the National Register of Historic Places because it does not meet the eligibility

criteria established by the National Park Service (NPS 1997). It lacks most of the typical or salient qualities to be considered a good example of a mid-twentieth-century vernacular cottage. The resource is an example of a highly-altered property within the SR 1 Interchange study area. The resource retains integrity of location and setting, but lacks integrity of design, materials, workmanship, association, and feeling, and does not convey historical or architectural significance. Along with the new siding, replacement windows, and new fixed shutters, these alterations have substantially changed the original character of the dwelling.

Property-specific and documentary research of the area in general did not reveal any associations between the L. Webb property and significant events or trends. The property is recommended not eligible for listing in the National Register under Criterion A for this reason. Historic research indicates that this property was associated historically with the Webb family in the Little Heaven/Frederica area during the twentieth century However, they do not appear to have been significant individuals; therefore, the property is recommended not eligible for listing under Criterion B. The L. Webb property does not display the distinctive characteristics of a type, style, or method of construction, nor does it represent the work of a master or possess high artistic value; therefore, it is recommended not eligible under Criterion C. Archaeological investigations have not yet been conducted on this property; therefore, the resource's eligibility under Criterion D (potential to yield information important to history or prehistory) cannot be assessed at this time.

Bibliography

Kent County Recorder of Deeds (KCDB)

Kent County Deed Books, Kent County Courthouse, Dover, Delaware.

National Park Service (NPS)

1997 National Register Bulletin 15: How to Apply the National Register Criteria for Evaluation. U.S. Government Printing Office, Washington, D.C.

Webb, Ruth

2004 Personal communication, July 26, 2004.